5.5.	Service	Log 5	Service	Package	C	1700	hun
------	---------	-------	---------	---------	---	------	-----

Date: 30:09-2013 Mileage 24.000 miles* | Age 48 months* 1) Service and inspections according to section 4.4 of this manual have been performed. 2) Body damage has been found on the vehicle as described on the next page. 3) The following factory required actions have been performed: - Rean bumpstops. - Bonangban neinfoncement. 4) The following additional actions have been performed: Invoice No. Customer Signature Dealer Signature Dealer Stamp

Edisonweg 2

3899 AZ ZEF Tel: +31 36 5358787 Fax:

* Cross out what does not apply

E pyles

NULLA TENACI INVIA EST VIA

1. VEHICLE PROVENANCE

This document has been issued exclusively and is valid only for the following vehicle (see Owner's Manual for location of identification labels):

Make	Spyker		
Туре	C8		
Version	Spyder		
VIN	XL9AA11G962363122		
Engine	4.2 LAR V8		
Engine code	BFM 035140		
Transmission code	0008072		
Exterior color code	OPH-E-001 Jet Block		
Interior color/trim code	OPH-I-69061 Ripstick Red.		
Additional specifications			

Date of delivery (dd/mm/yy):

1	2	0	4	4

Official Spyker Dealer Stamp: Spyker Automobielen B.V. Edisonweg 2
3899 AZ ZEEWOLDE Tel: +31 36 5358787 Fax: +31 36 5358780